Public Record – Summary Information For Regulated Underground Storage Tanks (USTs) Nevada Division of Environmental Protection (NDEP)

Date Posted To Web: April 6th, 2021

General Information:

Total Number of UST Facilities: 1,381

Total Number of USTs: 3,991

Summary of Information For On-Site Inspections:

Number of UST Facilities Inspected: 891

Inspection Period Dates: October 1, 2019 through September 30, 2020

Percent Compliance (TCR Combined measure): 17.2%

Note: The above tank and facility numbers were produced from NDEP's Database. Compliance inspections are conducted by NDEP staff in rural counties, the Southern Nevada Health District staff in Clark County, and the Washoe County District Health Department staff in Washoe County.

Please click on the following link for each UST implementing agency's contact information: http://ndep.nv.gov/bca/file/contacts 0608.pdf

Summary Information for Releases:

Number of Confirmed Releases: 7 (At 10 UST Facilities)

Release Reporting Period Dates: October 1, 2019 through September 30, 2020

Summary Information For Release Sources And Causes:

| | | Cause | | | | | | | | | | | | | | |
|---------------------|---|-------|-------|----|----------|----|------------------------|----|-----------|----|--------------------|----|-------|----|---------|------|
| Source | | | Spill | | Overfill | | Phys/Mech Damage ** | | Corrosion | | Install Problem | | Other | | Unknown | |
| | # | % | # | % | # | % | # | % | # | % | # | % | # | % | # | % |
| Tank | 5 | 71% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 5 | 100% |
| Piping | 2 | 29% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 2 | 100% |
| Dispenser | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% |
| STP * | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% |
| Delivery Problem | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% |
| Other | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% |
| Unknown | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% |
| Totals | 7 | 100% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 7 | 100% |

^{(# =} Number; Source % = Percent of source total number; Cause % = Percent of individual source (i.e. spill, overfill, etc.))

Note: Release source/causes data for the referenced reporting period were collected using NDEP's Project Tracking (PT) database and Nevada Petroleum Fund coverage applications.

Please click on the following link for NDEP database information and LUST file review procedures: http://ndep.nv.gov/admin/env info request.htm

^{*} STP = Submersible turbine pump/sump area; ** Physical/Mechanical Damage